

# Oil Field Environmental Incident Summary

**Incident:** 20140325160033 **Date/Time of Notice:** 03/25/2014 16:00

**Responsible Party:** BTA OIL PRODUCERS, LLC

**Well Operator:** BTA OIL PRODUCERS, LLC

**Well Name:** 20006 STATE 21-36H

**Field Name:** BEAVER CREEK

**Well File #:** 15724

**Date Incident:** 3/23/2014 **Time Incident:** 17:00

**Facility ID Number:**

**County:** GOLDEN VALLEY

**Twp:** 143

**Rng:** 103

**Sec:** 36

**Qtr:**

**Location Description:** SWD Facility

**Submitted By:** Pam Inskeep

**Received By:**

**Contact Person:** Pam Inskeep  
104 SOUTH PECOS  
MIDLAND, TX 79701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	88	Barrels	87	Barrels	87	barrels
Other						

**Description of Other Released Contaminant:**

N/A

**Inspected:**

**Written Report Received:** 1/9/2017

**Clean Up Concluded:** 3/25/2014

**Risk Evaluation:**

None

**Areal Extent:**

N/A

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Vac truck was immediately called. Recovered 87 BSW which was placed in tank onsite. Will hot oil & wash area. Fluid recovered from that operation will be disposed of at an approved facility.

**Wastes Disposal Location:** Fluids from the hot oil and wash will be disposed of at an approved facility.

**Agencies Involved:**

**Updates**

---

**Date:** 3/30/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.